



2cRelnoteStep4.doc

## Software Release Note for Step 4

### AT Version V433Q

Update 03/10/03

#### **New features**

↪ Same as 433

#### **Corrected problems (CP) / Changes in the AT command interface (CAT)**

Preliminary remark : The former bug identification refers to Release Note Step 4 (V433)

CP 1- 32k mode problem correction

#### **Known bugs**

↪ Same as 433

#### **Design Features**

↪ Same as 433